



**NOTIFICACIÓN NÚM. 1**

**SUBASTA FORMAL 22J-04684  
PARA LA ADQUISICIÓN DE SERVICIOS DE REPARACIÓN GENERAL DE LA  
INFRAESTRUCTURA DEL CDT DE LAJAS, ADSCRITO AL DEPARTAMENTO DE  
SALUD DEL GOBIERNO DE PUERTO RICO**

**Asunto: Fotos CDT de Lajas**

Se notifica a los licitadores interesados en participar en la subasta de referencia de la siguiente información:

- I. **Envío de las siguientes fotos: (VER ARCHIVO ADJUNTO).**
  - a. *Tubería Aislación de Sistema de Chiller*
  - b. *Flooring Vinyl Composition Tile (losas de piso en 2 cuartos distintos)*
  - c. *Vinyl Cove Base (zócalos de pared)*

*Estas fotos no representan trabajo adicional ni cambios al alcance del trabajo incluido en el pliego original de la subasta 22J-04684 del CDT de Lajas.*

Esta Notificación forma parte del pliego de Subasta Formal y tendrá que ser considerada junto con su Oferta. Todos los demás términos, condiciones y especificaciones permanecen sin alterar.

**Edmarie Avilés Almenas**  
Secretaria  
Junta de Subastas



Emitida hoy, 24 de octubre de 2022  
San Juan, Puerto Rico



Item 7 en Tabla de Cotizar






Item 7 en Tabla de Cotizar




Item 8 en Tabla de Cotizar: 60 LF Flooring demolition, vinyl or rubber cove base, straight section. Install; wall base, rubber, straight or cove, standard colors, 4" high, 1/8" thick (60 pies lineales de zócalos).




<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00	
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)	
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas		<b>GPS COORDINATES:</b> 18.03927 -67.05563




Lajas (CDT) Sign-in sheet



Lajas (CDT) entry sign




Lajas (CDT) front entrance




Lajas (CDT) acoustic ceiling tiles 2x2 looking toward front entrance


SITE INSPECTION PHOTO PAGE		DISASTER: DR4339PR		APPLICANT (FIPS#): 000-U40VB-00
INSPECTION DATE: 4 Dec 2018	WORK ORDER #: 27905	CATEGORY: E	COUNTY: Lajas	APPLICANT ADDRESS: Lajas Center for Diagnostics & Treatment (CDT)
SITE INSPECTOR(S): Steven Curtis, Juan Nomora, Mike Davis			DAMAGE # / DAMAGE NAME: 151665/CDT Lajas	GPS COORDINATES: 18.03927 -67.05563




Lajas (CDT) front waiting room single pane uninsulated slight tint aluminum fram glass window. Temporary tape fix.



Lajas (CDT) pump room




Lajas (CDT) 3-phase water pump motor




Lajas (CDT) water pump motor tag-pump 2

SITE INSPECTION PHOTO PAGE		DISASTER: DR4339PR		APPLICANT (FIPS#): 000-U4OVB-00
INSPECTION DATE: 4 Dec 2018	WORK ORDER #: 27905	CATEGORY: E	COUNTY: Lajas	APPLICANT ADDRESS: Lajas Center for Diagnostics & Treatment (CDT)
SITE INSPECTOR(S): Steven Curtis, Juan Nomora, Mike Davis			DAMAGE # / DAMAGE NAME: 151665/CDT Lajas	GPS COORDINATES: 18.03927 -67.05563




Lajas (CDT) 3-phase water pump motor-pump 4



Lajas (CDT) water pump motor tag-pump 4



Lajas (CDT) water pump motor tag-pump 4




Lajas (CDT) water pump motor control panel


<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00	
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)	
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas		<b>GPS COORDINATES:</b> 18.03927 -67.05563




Lajas (CDT) water pump control panel



Lajas (CDT) water pump control panel




Lajas (CDT) water pump control panel




Lajas (CDT) fire and local water supply line, single access point




<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas	<b>GPS COORDINATES:</b> 18.03927 -67.05563




Lajas (CDT) water pump and ground tank room



Lajas (CDT) CHILLER concrete wall enclosed pad




Lajas (CDT) CHILLER




Lajas (CDT) CHILLER information tag


SITE INSPECTION PHOTO PAGE		DISASTER: DR4339PR		APPLICANT (FIPS#): 000-U40VB-00
INSPECTION DATE: 4 Dec 2018	WORK ORDER #: 27905	CATEGORY: E	COUNTY: Lajas	APPLICANT ADDRESS: Lajas Center for Diagnostics & Treatment (CDT)
SITE INSPECTOR(S): Steven Curtis, Juan Nomora, Mike Davis			DAMAGE # / DAMAGE NAME: 151665/CDT Lajas	GPS COORDINATES: 18.03927 -67.05563




Lajas (CDT) chiller pipe insulation damage



Lajas (CDT) chiller pipe insulation condition none disaster related




Lajas (CDT) chiller pipe insulation condition none disaster related




Lajas (CDT) roof a/c split condensing unit, 9000 BTU, for IT server room


<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00	
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)	
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas		<b>GPS COORDINATES:</b> 18.03927 -67.05563




Lajas (CDT) roof a/c split condensing unit, 9000 BTU, for IT server room



Lajas (CDT) roof a/c split condensing unit, 9000 BTU, for IT server room




Lajas (CDT) SERVER ROOM1-cooled by rooftop condensing unit.



Lajas (CDT) SERVER ROOM-2 - cooled by rooftop condensing unit.

<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas	<b>GPS COORDINATES:</b> 18.03927 -67.05563




Lajas (CDT) roof temporary repair w/ insulation



Lajas (CDT) roof temporary repair w/ insulation




Lajas (CDT) roof temporary repair w/ insulation



Lajas (CDT) roof temporary repair w/ insulation


<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00	
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)	
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas		<b>GPS COORDINATES:</b> 18.03927 -67.05563




Lajas (CDT) roof temporary repair w/ insulation



Lajas (CDT) roof temporary repair w/ insulation, roof drainage




Lajas (CDT) roof temporary repair w/ insulation




Lajas (CDT) trees from municipality side of back of facility fence has grown through, not disaster related damage


<b>SITE INSPECTION PHOTO PAGE</b>		<b>DISASTER:</b> DR4339PR		<b>APPLICANT (FIPS#):</b> 000-U40VB-00
<b>INSPECTION DATE:</b> 4 Dec 2018	<b>WORK ORDER #:</b> 27905	<b>CATEGORY:</b> E	<b>COUNTY:</b> Lajas	<b>APPLICANT ADDRESS:</b> Lajas Center for Diagnostics & Treatment (CDT)
<b>SITE INSPECTOR(S):</b> Steven Curtis, Juan Nomora, Mike Davis			<b>DAMAGE # / DAMAGE NAME:</b> 151665/CDT Lajas	<b>GPS COORDINATES:</b> 18.03927 -67.05563



Lajas (CDT) trees from municipality side of back of facility fence has grown through, not disaster related damage to building



Lajas (CDT) trees from municipality side of back of facility fence has grown through, not disaster related damage



Lajas (CDT) trees from municipality side of back of facility fence has grown through, not disaster related damage

